All data for Victoria Technology, Inc as of 03/10/2022

Help for this report This report contains most of the data from the facility record including inspections, MITs, permit information and project status. You can select/copy and "paste special- unformatted text" all or part of this page to a text document to start correspondence about the facility.

Facility

Victoria Technology, Inc 5857 S. Kyrene Road Tempe, AZ 85283

GIS: 33.37, -111.94

Local Identifier: APN 301 03 015

UIC File ID: none Tribal Land: No

Ownership: Private - Business or other for-profits

Contacts

Contact Type: Owner Raymond Jasper Victoria Technology, Inc. 6916 South Los Feliz Drive Tempe, AZ 85283 rayjasper@msn.com

Co-Regulators

Project Status and Comments

Status	Action Date	Followup Date	Action Needed	First Mid	Last	Comments	Updated
Inventory Only	01/31/2011	-	-	-	-	We are installing the new injection/remediation wells for the former owner (Capitol Castings now Victoria Technology, Inc.). The proposed injection wells are for the treatment of former gasoline leaking underground storage tank. Historic remediation was conducted, but, dissolved phase VOCs remained elevated in the source area. Therefore, the proposed remedial strategy is in-situ chemical oxidation using sodium persulfate. The injection wells and remedial strategy were approved by Thomas DiDimizio project manager and interim manager of the Arizona Department of Environmental Quality (ADEQ) Voluntary Remediation Program (VRP). Christopher.Shepherd@arcadis-us.com	01/31/2011

Named Wells

Count/	Well Name
2	No data

Well Summary

2 - Active - 5X26 Aquifer Remediation - as of 01/31/2011

Other Ground Water Considerations For Facility

No Non-UIC Discharges recorded.

Inspections in the last 10 Years

No inspections recorded in iWells database over the last 10 years.

Class V Closure Action(s)

No Closure actions have been recorded for wells at this facility.

Mechanical Integrity Tests

No mechanical integrity tests found.

Permit & Permit Activity

No permit or permit activity found.

Permit History

No permit or permit activity found.

Violations

No violations found.

Attachments - Not Confidential

No attachments have been added.

Enforcement Actions

No Enforcement data has been added.

9439 LJANES Victoria Technology, Inc 01/31/2011

release 2.022.2CustomizeSet Screen Reader Mode On